

COUNTY OF LOS ANGELES
DEPARTMENT OF COUNTY ENGINEER
BUILDING AND SAFETY DIVISION

INVESTIGATION REPORT

LOCATION OF PROBLEM 11025 COOLHURST

LOCALITY WHITTIER

DESCRIPTION OF PROBLEM DRAINING POOL

ONTO NEIGHBORS PROPERTY
(BACKWASH)

REQUESTED BY ALON PHONE ~~814-1111~~

ADDRESS _____

RECEIVED BY M. NOBLES DATE 8/19/92

REFERRED TO _____ DATE _____

REPORT OF INVESTIGATION _____

NO ONE HOME,
FURNITURE AGAINST FENCE
NOT VISIBLE- NO SIGN
OF RUN-OFF.

INVESTIGATOR M. NICH TITLE DET DATE 9/4/92

COPY SENT TO _____ TITLE _____ DATE _____

REPORT PHONED TO _____ TITLE _____ DATE _____